

FIG. 1




FIG. 2

FIG. 2 is a block diagram of a mail notification system.





FIG. 3



[3]

FIG. 4




FIG. 5

image information








FIG. 6

6/8

Subject: EMERGENCY from HomeSec
Date: Mon,28 May 2001 10:21:22
+0900(JST)
From: HomeSec
To: 09012345678@abc.ne.jp

~~玄関で異常事態が発生しました。~~
image
画像URL
<http://www.homesec12345.ne.jp/picture/20010528/10-21-02>

~~返信先アドレス~~ response-to address
homesec12345@xvz.ne.jp

An abnormality has occurred at the front door

menu

select

return

FIG. 6

FIG. 7

